

ST 5151 - WORLD MAP APPLICATION INSTRUCTIONS



SIZE

approx. 12 feet wide by 8 feet tall

PAINTERS & TIME

1-2 painters for 4-5 hrs

INCLUDED IN THE BOX:

3 Stencil Sheets (3 pieces)







BEFORE YOU START PAINTING:

Please completely read the Application Instructions & prepare your surfaces as recommended.



STEP 1

Place STENCIL A in your desired location.



STEP 2

Paint the borders. **DO NOT PAINT THE CONTINENT LABELS YET**. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove the stencil sheet.



STEP 3

Align STENCIL B using the etched guidelines to align with the painted portion from STENCIL A.



STEP 4

Paint the borders. **DO NOT PAINT THE CONTINENT LABELS YET**. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove the stencil sheet.



STEP 5

Align STENCIL C using the etched guidelines to align with the painted portion from STENCIL B.



STEP 6

Paint the borders. **DO NOT PAINT THE CONTINENT LABELS YET**. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove the stencil sheet.



STEP 7

Fill-in the bridges to make the borders complete.

TIP: You can use the enclosed bridge tools to help fill-in the gaps.



STEP 8

Paint the inside shapes of the map, with each continent painted a unique color. Repeat 1-2 times to achieve desired vividness, allowing the paint to dry between each application. Before preceding to the next step, make sure the paint on the surface is completely dry.



STEP 9

Align STENCILS A, B, & C to the painted surface.



STEP 10

Paint the continent labels. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove the stencil sheets.

CONGRATULATIONS!

YOU FINISHED PAINTING "WORLD MAP"!
Your finished painting should look like the image below.



Have any questions?

We're here to help – call us at (800) 681-0684! Visit our website: FITANDFUNPLAYSCAPES.COM